



i4500R / i5500 Firmware V2.3.8p1 Release Note

[Release Date]

January,10, 2011

[Bug fixed]

1. Fix Marvell SATA chipset issue. This issue would cause some HDD can't be recognized after controller reboot.

[Feature change]

1. Break the 2TB physical disk limitation on Marvell SATA chipset model.