

## i4500R / i5500 Firmware V2.3.0 Release Note

### **[Release Date]**

**July.25, 2008**

### **[Bug fixed]**

1. The "#Session" column still shows "0" in Web UI after we scan all volumes in Disk Management.
2. iSCSI NIC IP can not reset to factory default.
3. [Console\_ui] Press "Change secret" cause console\_ui logout.
4. Select to change the "French" language, it's failed to browse this /User data volume page.
5. [Web\_ui] It hangs-on at "Import in progress..." after click config import.
6. RAID 0+1 can not set dedicated spare in console\_ui.
7. After "spin up and spin down" test for several times, the hitachi disk will be disable.

### **[Feature change]**

1. Change MTU setting to Jumbo Frame Support (iSCSI frontend models)  
(Only enable/disable Jumbo Frame, no Jumbo Frame size setup).
2. Support French in Web UI (all models)

### **[Known Issue]**

1. When the system name setting include the symbol " ' ", some errors occur in Web and console UI.